

30° branch plates, galvanised


Diameter: ø80 – ø1000 mm.

Galvanised branch plates are made of 0.90 mm sheet metal.

State A-, B- and C dimensions when ordering.
Options are limited by $A = C$, and $A \geq B$.
 $A = C$ must be max. 1000 mm.

The branch determines the length of L1.
Branch plates are always straight with the branch centrally located.

If $B < 300$: $X = 50$ mm
If $B > 300$: $X = 100$ mm



Calculating L2 and L3:

L1 = see table

$$L2 = \frac{1}{2} \times \left(L1 - \frac{A}{\tan \alpha} \right)$$

$$L3 = \frac{L1 - L2}{\cos \alpha} - \left(\frac{B}{2} \times \tan \alpha \right)$$

Example:

$A = 700$, $B = 350$, $C = 700$

$L1 = 950$ mm

$$L2 = 0,5 \times \left(950 - \frac{700}{\tan 29,6} \right) = 0,5 \times (950 - 1232,22)$$

$L2 = -141,11$ p - 141 mm

$$L3 = \frac{950 + 141}{\cos 29,6} - \left(\frac{350}{2} \times \tan 29,6 \right) = 1254,75 - 99,41$$

$L3 = 1155,34$ p 1155 mm

Dimensions					
A = C mm	B mm	L1 mm	L2 mm	L3 mm	α
Select (80 - 1000)	80	350	Calculate	Calculate	28,0
	100	350			28,8
	120	350			28,8
	125	400			29,0
	140	450			29,1
	150	450			29,2
	160	450			29,2
	180	550			29,3
	200	550			29,3
	225	600			29,4
	250	750			29,5
	275	750			29,6
	300	750			29,6
	315	850			29,6
	350	950			29,6
	400	1050			29,7
	450	1250			29,7
	500	1250			29,7
	550	1450			29,8
	600	1450			29,8
650	1650	29,8			
700	1650	29,8			
750	1850	29,8			
800	1850	29,9			
850	2050	29,9			
900	2050	29,9			